Prepared By:

City of Charlotte Housing & Neighborhood Services 600 E. Trade Street Charlotte, NC 28202 (704) 336-7600

(704) 336-7600							
Property Details							
Address:	7711 Cedar Bluff Ln Charlotte, NC 28227		Owner: Owner Phone:		y Payne 737-6820		
Structure Type:	Single Unit		Program(s):	SHFY	2020	1	
Square Feet:	1224			SHFY	21		
Year Built:	1978	•					•
Property Value:	84000						
Tax Parcel:	13507132	,					
Census Tract:							
Property Zone:							
Repairs							
<u>Description</u>			<u>F</u>	Floor	Room		Exterior
All Contractor's Projec	t Requirements						
The contractor is respon	sible for project requirements, including	but limite	d to:				
COVID-19 Process							
Obtaining all permits req	uired. Said permits shall include all item	ns in this s	cope of work.		,	,	
Provide temporary toilet	facilities from job start until the completi	ion of wor	k.				
	ff dumpsters as needed without damagli epair any evidence of the dumpsters us	-			_		
		Bid Cost	*	_X		=	
			Base	(Quantity		Total Cost
Front Door & Rear Util	ity Room Doors						
dead bolt and lever hand	ame and threshold. Install new Energy a lled door hardware keyed alike. Install w t. This installation to include repairing a	vide peep	sight. New casin	ig and s	hoe moldir	ng will mat	tch existing.
		Bid Cost	· :	х			
			Base		Quantity	P	Total Cost

Rear-Vinyl French Doors to Patio

Remove and dispose of existing door, frame and threshold. Install new Energy Star rated pre-hung exterior vinyl siding patio door with screen and locking hardware. Insulate cavity. New casing and shoe molding will match existing. This installation is to include repairing any damaged header, door framing, wall framing, sub-floor, floor joists, band joists, and sill.

	Bid Cost:		X=	
		Base	Quantity	Total Cost
Vinyl Window				
Do not replace triangular Windows above front Door				·
Dispose of window units and any security bars. Field measure, windows including half screens. Insulate rough opening. Install Exterior trim to be wrapped in PVC coated aluminum coil as ne installation is to include repairing any damaged header, framing joists and sill. Any windows replaced in a bathroom must have	new extension eded. Repair a g (to include kir	jambs, casin Ill areas distur ng studs, jack	g and sill as needed bed by removal and	I, prime and paint. I installation. This
·	Bid Cost:		X=	
		Base	Quantity	Total Cost
Handrail Install & replace missing brick - Front steps	nazione a finazione soni necessi i visios e estatorne assesse e sonici	ne visit innin nivos de entreprimentario e princis.º	perioder of the page of the regions of the page of the Co. White	terna y aux brook aankas (kosta (real arrib) on karankii (b. 78)
Install handrail , on BOTH SIDES , Exterior front steps to Code	e.			
	Bid Cost:		x =	
	Dia 003t	Base	Quantity	Total Cost
Exterior Deck Replacement- REAR			and the second second second second second second second second	
Remove rear-deck. Replace with 120 sq ft treated lumber Deck and railings, as we and in accordance with Appendix M of NC Building Code.	ell as new steps	and railings	should be constructe	ed of treated lumber
	Bid Cost:		X=	
		Base	Quantity	Total Cost
Exterminate Termites	and states, resource resources to sever comple	The second property with the second		Control and a second control a
Exterminate for termites. Drill and patch foundation and paver year guarantee with an optional yearly renewable warranty for			minator must be lice	nsed and provide a 1
	Bid Cost:		X=	
		Base	Quantity	Total Cost
ananang ay e ing kanggan pangganan na mang ay ananggan ang ang mang ang ang ang anang mang m	THE STATE OF THE STATE OF THE STATE	no description of the factors for all time	್ರ ಪಡಿಸಲಾವ ಕರಣಗಳ ನೀಗೆ ಕಡೆಗೆ ಒಡುವಾರ ವಿಶ್ವೆಗಳ ತಿಕೆಸಲ್ ಮತ್ತೆ ಗಳಿಗೆ ಬಡುವ	ar fill brakum promunus om kilosoft provincia o provincia meneri iki ese 1949 p

Lawn Landscaping, Tree Removal

- 1. Remove hardwood tree in front of sidewalk to front door, back-fill hole level with clay, seed & straw.
- 2. Remove hardwood tree just behind rear-deck (back-fill hole level with clay, seed & straw)
- 3. Cut all rear-yard seedlings below ground level. Cut grass, & trim

	Bid Cost:		X =	Total Cont
	production of the state of the	Base	Quantity	Total Cost
Rear Porch Doorway SHED-ROOF			•	
Construct a shed roof 3 feet wider than the glass doors openiall exposed wood to match house colors, match trim dimensionatch.				
•	Bid Cost:		X=	
		Base	Quantity	Total Cost
Replace/ Refasten Any Loose/ Missing Or Decayed Exter	ior Lumber			
 Remove & replace any decayed wood products (T111) a Replace all decayed plate & band. Stain to match. Enclose any holes in front porch columns. Paint/stain to m 		,		· ·
	Bid Cost:		x =	
		Base	Quantity	Total Cost
Custom Shelf Installation		ACCESSOLALISMS AND RESIDENCE OF SECURIOR	manyarangan dang palangga as pagtatanggatiba. W	ikker mila milamanan sasamanninin mel-dirike bila bila (1909 kila kila kila kila kila kila kila kila
 Clean out items from Rear Utility room floor and front - mid Install a wooded shelving unit, the length of the wall (from Shelves to be 7/16" plywood. 2 Shelves high. All extra/ stored items from the two front bedrooms to be stored. 	front of house to h	nall) 3 feet d	leep. Anchor the fra	aming to the wall studs.
	Bid Cost:		X =	
		Base	Quantity	Total Cost
Floor System Repair	and by parameters are made point 14 or 1991, as one		and the constructions of a second of the decision of	
Living room / Dining room. Remove all stored items. Items to go into shed, Utility room of Ensure sub-floor is level. Work may include installation of some				acement.
	Bid Cost:		x=	

Living/Dining Room / Master Bath/ Laundry Room & Hallway

Living /Dining Room / Master Bath/Laundry Room & Hallway

Install 25 year warrantied resilient floor covering per manufacturer's specifications. Flooring material is to be vinyl interlocking planks and be waterproof. Include transitions and painted or stained wood quarter-round at all perimeters to complete installation.

	Bid Cost:		Х		
		Base	Quantity	y	Total Cost
Braille / Sound Thermostat			er total a transfer for t		
Replace hallway Thermostat with a Braille / Sound Thermosta	at				
	Pid Cost:		Υ	=	
	Bid Cost:	Base	Quantity	 У	Total Cost
Cabinet Repair - Construct Drawer	renerrung tumpakan propinsionen und Societ	in Productive Street, and didden & Address.		erandoner (f. 16. 16. 16. 16. 16. 16. 16. 16. 16. 16	New of proposition businesses in the Co
Construct a Drawer to fit the Bathroom Vanity. Finish with ma	atching semi-glo	ss low-VOC	paint.		
•					
	Bid Cost:	Base	_X Quantit		Total Cost
		Dase	Quantity	y 	Total Cost
Master Bedroom					
Completely demo the existing bathroom. Remove all plumbin coverings to the framing.	ng and electrical	fixtures, doo	rs and trim, and	ceiling,	wall, and floor
Damage extends outside of the bathroom. Include repair of a	all components a	ssociated wi	th this damage		
Repair or replace all framing as necessary, drywall, moldings Building Code.	to meet the req	uirements of	the Constructio	n Specifi	cations and the
•	el ring)		the Constructio	n Specifi	cations and the
Rebuild the bathroom complete with all the following features *floor, wall, and ceiling insulation at locations required by the *ceiling mounted fan vented through the roof *switched light fixture over the vanity *GFCI outlet per Code *Fiberglass stand-up shower enclosure *drywall and finish walls and ceiling *baseboard and shoe mold at standard locations *1.6 gpf commode 17" *24" vanity with cultured marble top and single handle faucet *3 piece bath hardware set (towel bar, paper holder, and tow *mirror over vanity *walls and ceiling painted semi-gloss per Construction Specific * all un-joined 1/4 round trim ends will be cut at a 45 and doc	el ring) fications. uble-painted	ecifications			
Rebuild the bathroom complete with all the following features *floor, wall, and ceiling insulation at locations required by the *ceiling mounted fan vented through the roof *switched light fixture over the vanity *GFCI outlet per Code *Fiberglass stand-up shower enclosure *drywall and finish walls and ceiling *baseboard and shoe mold at standard locations *1.6 gpf commode 17" *24" vanity with cultured marble top and single handle faucet *3 piece bath hardware set (towel bar, paper holder, and tow *mirror over vanity *walls and ceiling painted semi-gloss per Construction Specificall un-joined 1/4 round trim ends will be cut at a 45 and doc * supply vent	el ring) fications. uble-painted	ecifications		itions and	

Combination CO / Smoke Detector Hard Wired

Install a hard wired combination carbon monoxide and smoke detector with battery back up.

	Bid Cost:	X	<u> </u>	
		Base	Quantity	Total Cost
Smoke Detector Hard Wired	unikuwa na propogogo na diabandi u ilianda perundah diabah di ilianda perundah diabah di ilianda diabah di ili	an emercial for the terms of	the state of the s	and the control of th
nstall UL approved, interconnected, ceiling mounted pattery backups in bedrooms and outside of sleeping		permanently	wired into a recept	acle boxes with
	Bid Cost:			
		Base	Quantity	Total Cost
2 front bedroom ceiling light Installation	a day usaa dagamaa daga usaa dayaa ahuu ta'hoola ka 19 may hooka ka k	enter to the tracket. The	i meletini i umummi fallocati formittaksi mora Afrikansa A	and the control of th
nstall a LED ceiling light in the front 2 bedroom ceilin	ngs. Switch plate operated.			
nstall a LED ceiling light in the front 2 bedroom ceilin	ngs. Switch plate operated. Bid Cost:	>	(=_	
nstall a LED ceiling light in the front 2 bedroom ceilin		Base	(=_ Quantity	Total Cost
				Total Cost
nstall a LED ceiling light in the front 2 bedroom ceilin Certification Contractor Name:				Total Cost